

## APPENDIX E: SITE RECONNAISSANCE PHOTOGRAPHS





**Photograph 1 View of the Velocity Iron & Metal South of the Alignment along Road 24**



**Photograph 2 View of Agricultural Land along Avenue 19 Looking North**



**Photograph 3 View of the Avenue 21 1/2 from the SR 99 Overpass Looking West**



**Photograph 4 View of Madera Disposal Systems, Inc. at 0.25 Mile Buffer from Alignment, Looking West**



**Photograph 5 View of the Agricultural Land along Avenue 20 Looking West**



**Photograph 6 View of the Tony Brasilia Dairy Facility along Alignment Looking East**



**Photograph 7 View of the Central Valley Composting Facility North of the Alignment in El Nido**



**Photograph 8 View of Hugh's Flying Service Facility along SR 152 and Red Top Road**



**Photograph 9 View of SR 152 Looking East**



**Photograph 10 Representative View of Agricultural Land and Kwik Service Gasoline Service Station Looking South from SR 152**



**Photograph 11 View of Road 24 and Avenue 23 Intersection**



**Photograph 12 View of Tony Machado Dairy Facility along Avenue 23**





**Photograph 13 View Domingo's Ribeiro Dairy Facility along Avenue 25**



**Photograph 14 View of Agricultural Land from SR 99**



**Photograph 15 View of the Lockwood Seed Company Facility**



**Photograph 16 View of SR 99 Looking North**



**Photograph 17 View of Diesel County Truck Stop Facility along SR 99**



**Photograph 18 View of the Agricultural Facility off SR 99 near the Northern Alignment Terminus**